

L Number	Hits	Search Text	DB	Time stamp
1	271	702/104.cccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 09:24
8	25	702/104.cccls. and (measur\$5 or determin\$3 or detect\$3 or obtain\$3) with position\$3 with (element\$1 or object\$1 or tool\$1 or workpiece\$1)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 09:26
-	156907	(measur\$5 or determin\$3 or detect\$3 or obtain\$3) with position\$3 with (element\$1 or object\$1 or tool\$1 or workpiece\$1)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 09:24
-	590	((measur\$5 or determin\$3 or detect\$3 or obtain\$3) with position\$3 with (element\$1 or object\$1 or tool\$1 or workpiece\$1)) and ((voltage with monitor\$3) and scan\$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:40
-	263	((measur\$5 or determin\$3 or detect\$3 or obtain\$3) with position\$3 with (element\$1 or object\$1 or tool\$1 or workpiece\$1)) and ((voltage with monitor\$3) and scan\$4)) and ((element\$1 or object\$1) with (movable or moving or movement))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:42
-	185	((measur\$5 or determin\$3 or detect\$3 or obtain\$3) with position\$3 with (element\$1 or object\$1 or tool\$1 or workpiece\$1)) and ((voltage with monitor\$3) and scan\$4)) and ((element\$1 or object\$1) with (movable or moving or movement)) and ((suppl\$3 with voltage) or (voltage with source))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:26
-	1	((measur\$5 or determin\$3 or detect\$3 or obtain\$3) with position\$3 with (element\$1 or object\$1 or tool\$1 or workpiece\$1)) and ((voltage with monitor\$3) and scan\$4)) and ((element\$1 or object\$1) with (movable or moving or movement)) and ((suppl\$3 with voltage) or (voltage with source)) and ((scanning adj unit) with (position with calculate\$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:32
-	3	((measur\$5 or determin\$3 or detect\$3 or obtain\$3) with position\$3 with (element\$1 or object\$1 or tool\$1 or workpiece\$1)) and ((voltage with monitor\$3) and scan\$4)) and ((element\$1 or object\$1) with (movable or moving or movement)) and ((suppl\$3 with voltage) or (voltage with source)) and ((scanning adj unit))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:32
-	69492	(measur\$5 or determin\$3 or detect\$3 or obtain\$3 or monitor\$3) with position\$3 with (elements or objects or tools or workpiece\$1 or units)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:39
-	234	((measur\$5 or determin\$3 or detect\$3 or obtain\$3 or monitor\$3) with position\$3 with (elements or objects or tools or workpiece\$1 or units)) and (voltage with (suppl\$3 or source) with scan\$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:08
-	112	((measur\$5 or determin\$3 or detect\$3 or obtain\$3 or monitor\$3) with position\$3 with (elements or objects or tools or workpiece\$1 or units)) and (voltage with (suppl\$3 or source) with scan\$4)) and ((element\$1 or object\$1 or tool\$1) with (movable or moving or movement))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:43

	53	((((measur\$5 or determin\$3 or detect\$3 or obtain\$3 or monitor\$3) with position\$3 with (elements or objects or tools or workpiece\$1 or units)) and (voltage with (suppl\$3 or source) with scan\$4)) and ((element\$1 or object\$1 or tool\$1) with (movable or moving or movement))) and (calculat\$3 or evaluat\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:01
	3	((((measur\$5 or determin\$3 or detect\$3 or obtain\$3 or monitor\$3) with position\$3 with (elements or objects or tools or workpiece\$1 or units)) and (voltage with (suppl\$3 or source) with scan\$4)) and ((element\$1 or object\$1 or tool\$1) with (movable or moving or movement))) and (calculat\$3 or evaluat\$3)) and (((start adj up) or (start-up) or (switch\$3 with on) or (turn\$3 with on) or initial\$2) same ((check\$3 or inspect\$3 or verify\$4) with voltage))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:11
	1	((((measur\$5 or determin\$3 or detect\$3 or obtain\$3 or monitor\$3) with position\$3 with (elements or objects or tools or workpiece\$1 or units)) and (voltage with (suppl\$3 or source) with scan\$4)) and ((element\$1 or object\$1 or tool\$1) with (movable or moving or movement))) and (calculat\$3 or evaluat\$3)) and (((start adj up) or (start-up) or (switch\$3 with on) or (turn\$3 with on) or initial\$2 or (power adj up) or (power adj on)) same ((check\$3 or inspect\$3 or verify\$4 or examin\$3) with voltage with scan\$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:35
	9	((measur\$5 or determin\$3 or detect\$3 or obtain\$3 or monitor\$3) with position\$3 with (elements or objects or tools or workpiece\$1 or units)) and (voltage with (suppl\$3 or source) with scan\$4)) and (((start adj up) or (start-up) or (switch\$3 with on) or (turn\$3 with on) or initial\$2 or (power adj up) or (power adj on)) same ((check\$3 or inspect\$3 or verify\$4 or examin\$3 or measur\$5) with voltage))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:25
	217	((measur\$5 or determin\$3 or detect\$3 or obtain\$3 or monitor\$3) with position\$3 with (elements or objects or tools or workpiece\$1 or units)) and (((start adj up) or (start-up) or (switch\$3 with on) or (turn\$3 with on) or initial\$2 or (power adj up) or (power adj on)) same ((check\$3 or inspect\$3 or verify\$4 or examin\$3 or measur\$5) with voltage))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:27
	20	((measur\$5 or determin\$3 or detect\$3 or obtain\$3 or monitor\$3) with position\$3 with (elements or objects or tools or workpiece\$1 or units)) and (((start adj up) or (start-up) or (switch\$3 with on) or (turn\$3 with on) or (power adj up) or (power adj on)) same ((check\$3 or inspect\$3 or verify\$4 or examin\$3 or measur\$5) with voltage))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:28
	796	((start adj up) or (start-up) or (switch\$3 with on) or (turn\$3 with on) or (power adj up) or (power adj on)) same ((check\$3 or inspect\$3 or verify\$4 or examin\$3 or monitor\$3 or detect\$3) with voltage with (suppl\$2 or source))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:40

-		15	((start adj up) or (start-up) or (switch\$3 with on) or (turn\$3 with on) or (power adj up) or (power adj on)) same ((check\$3 or inspect\$3 or verify\$4 or examin\$3 or monitor\$3 or detect\$3) with voltage with (suppl\$2 or source))) and ((sufficient or stable) with voltage with supply)) and (position with (measur\$5 or determin\$4 or detect\$3 or calculat\$3 or evaluat\$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:43
-		144	((start adj up) or (start-up) or (switch\$3 with on) or (turn\$3 with on) or (power adj up) or (power adj on)) same ((check\$3 or inspect\$3 or verify\$4 or examin\$3 or monitor\$3 or detect\$3) with voltage with (suppl\$2 or source))) and ((sufficient or stable) with voltage with supply)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:57
-		1	((start adj up) or (start-up) or (switch\$3 with on) or (turn\$3 with on) or (power adj up) or (power adj on)) same ((check\$3 or inspect\$3 or verify\$4 or examin\$3 or monitor\$3 or detect\$3) with voltage with (suppl\$2 or source))) and ((sufficient or stable) with voltage with supply)) and (defined with load with voltage)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:57
-		48	((start adj up) or (start-up) or (switch\$3 with on) or (turn\$3 with on) or (power adj up) or (power adj on)) same ((check\$3 or inspect\$3 or verify\$4 or examin\$3 or monitor\$3 or detect\$3) with voltage with (suppl\$2 or source))) and ((sufficient or stable) with voltage with supply)) and (load with voltage)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:58
-		28	((start adj up) or (start-up) or (switch\$3 with on) or (turn\$3 with on) or (power adj up) or (power adj on)) same ((check\$3 or inspect\$3 or verify\$4 or examin\$3 or monitor\$3 or detect\$3) with voltage with (suppl\$2 or source))) and ((sufficient or stable) with voltage with supply)) and (load with voltage)) and (resistance)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:04
-		2	((start adj up) or (start-up) or (switch\$3 with on) or (turn\$3 with on) or (power adj up) or (power adj on)) same ((check\$3 or inspect\$3 or verify\$4 or examin\$3 or monitor\$3 or detect\$3) with voltage with (suppl\$2 or source))) and ((sufficient or stable) with voltage with supply)) and (load with voltage)) and (resistance)) and (second adj time)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:04
-		41	((measur\$5 or determin\$3 or detect\$3 or obtain\$3 or monitor\$3) with position\$3 with (elements or objects or tools or workpiece\$1 or units)) and (read\$3 with graduation with position)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:09
-		15	((measur\$5 or determin\$3 or detect\$3 or obtain\$3 or monitor\$3) with position\$3 with (elements or objects or tools or workpiece\$1 or units)) and (read\$3 with graduation with position)) and (light adj source)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:16
-		2	3644700.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2003/02/12 00:16

-	4	4219719.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB USPAT	2003/02/12 00:17
-	2	6462855.pn.	USPAT	2003/02/12 00:18
-	1	"5995246".PN.	USPAT	2003/02/12 00:18
-	1	"5929891".PN.	USPAT	2003/02/12 00:18
-	2	6353397.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB USPAT	2003/02/12 00:18
-	1	"6043768".PN.	USPAT	2003/02/12 00:19
-	1	"5532582".PN.	USPAT	2003/02/12 00:19
-	1	"5451940".PN.	USPAT	2003/02/12 00:19
-	1	"5012436".PN.	USPAT	2003/02/12 00:20